## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,727,627 B1 APPLICATION NO. : 10/019286

: 10/019286 : April 27, 2004

DATED : April 27, 2004 INVENTOR(S) : K. Sasaki et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 36, claim 14 should read – The synchronous motor as claimed in claim 1, wherein the slots positioned adjacent to the center points of the rotor magnetic poles having shorter radial lengths than the slots positioned adjacent to the end points of the rotor magnetic poles.

Signed and Sealed this

Page 1 of 1

Twenty-second Day of August, 2006

JON W. DUDAS Director of the United States Patent and Trademark Office